

**TOP SECRET****PRIORITY**

OUT56607

TOP SECRET 021950Z

PRIORITY  5371

IDEALIST

ATTENTION: 

SUBJECT: EVALUATION OF MISSION C425C

1. CAMERA 119 WAS USED IN MISSION C424C FLOWN ON 31 JULY 1965. PROCESSING WAS ACCOMPLISHED BY EASTMAN KODAK COMPANY.

## 2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: SEVERAL ABRASIONS OCCUR ON THE BASE SIDE, AND PARALLEL TO THE MAJOR AXIS OF THE FILM ON FRAMES 1/100 AND 130/150. THERE IS A WAVERING PLUS DENSITY STREAK THAT OCCURS IN FRAMES 57/65. A REFLECTION FROM THE VERTICAL DOT INDICATOR IS PRESENT THROUGHOUT THE MISSION. EMULSION DEFECTS ARE PRESENT IN FRAMES 318 AND 1873. AN EMULSION DIG IS LOCATED IN FRAME 666 AND EMULSION LIFTS ARE IN FRAMES 1463, 1532 AND 1562. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 200/201, 975/976 AND 1863/1864.

C. 9L SIDE: THE 1L POSITION INDICATOR LAMP DID NOT OPERATE THROUGHOUT THE MISSION. TWO DEEP ABRASIONS ARE ON THE OUTBOARD EDGE OF FRAME 223. FINE PLUS DENSITY ABRASIONS ARE PRESENT ON THE BASE OF PART NUMBERS 1, 2, AND 4. THERE ARE SEVERAL GROUPS OF THESE RANGING FROM 1/2 TO 3/4 INCHES APART BEGINNING AT THE HEAD OF EACH ROLL AND ENDING 80 TO 100 FRAMES INSIDE THE ROLL. SLIGHT

1965 SEP 2 20 08Z 13 SEP 1965

COPIES RECEIVED		
Cy No.	Office	Act.
✓	File	
	CS	25X1
	ADMIN	
	SEC FR	25X1
	PA-S	
	CSJ	
	IPD	
	PD	
	PSD	
3,4	PSD-ICB	
	TID	
	PID	
	PAG	
	DIAX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

**TOP SECRET**

GROUP 25X1  
Excluded from automatic  
downgrading and  
declassification

IRREGULAR ABRASIONS ARE LOCATED ON THE BASE OF FRAME 272. A BAND OF FOG PERPENDICULAR TO THE MAJOR AXIS APPEARS INSIDE THE FORMAT ON FRAME 77. A MINUS DENSITY COMET IS PRESENT ON FRAMES 363 AND 1599. FRAME 1903 CONTAINS SMALL EMULSION LIFTS. A PLUS DENSITY STREAK TWO INCHES IN LENGTH AND TWO INCHES FROM THE OUTBOARD EDGE IS LOCATED ON FRAMES 1012 AND 1013. HEAT SPLICES ARE BETWEEN FRAMES 411/412 AND 1203/1204.

D. BOTH SIDES: THE VERTICAL DOT INDICATOR IS BLOOMED. EDGE FOG IS PRESENT ON BOTH EDGES THROUGHOUT THE MISSION. ROLLER CHATTER IS CONTINUOUS ON THE INBOARD EDGE OF THE FILM. TITLE TRANSFER OCCURS IN TWO SEPARATE STREAKS THOUGHOUT. SMEAR POSSIBLY DUE TO VEHICLE MANEUVERS IS NOTED ON FRAMES 1045 AND 1514. THE LAST TITLED FRAME IS 1904.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS AND ATMOSPHERIC CONDITIONS DEGRADE OR OBSCURE APPROXIMATELY 25 PERCENT OF THE MISSION.

T O P S E C R E T

/END OF MESSAGE/